

# Workgroup Manager for Pro/ENGINEER Product Compatibility

This document defines the versions of Pro/ENGINEER that are supported with Windchill Foundation & PDM, Windchill PDMLink, and Windchill ProjectLink.

## Windchill 8.0 and Pro/INTRALINK 8.0 Series Compatibility

		Pro/ENGINEER <sup>6</sup> Release			Notes
		Wildfire 2.0	Wildfire 3.0	Wildfire 4.0	
Windchill <sup>6</sup> 8.0 Release	F000	M130+ (See Notes 4,5)			
	M010	M170+			
	M020	M200+	F000+		With 8.0 M020 Pro/ENGINEER Wildfire 2.0 M210+ and Pro/ENGINEER Wildfire 3.0 M030+ are now supported on 64-bit Windows XP. See Note 10 in the platform support matrix (below) for more details.
	M030	M220+	M030+		
	M040	M250+	M070+		
	M045	M270+	M110+		Microsoft Vista support will be available starting with Pro/ENGINEER Wildfire 3.0 M120 and 8.0 M045
	M050	M280+	M140+	F000+	

## Windchill 7.0 Series Compatibility

		Pro/ENGINEER Release				Notes
		2001	Wildfire	Wildfire 2.0	Wildfire 3.0	
<b>Windchill 7.0 Release</b>	<b>F000</b>	2003450+	2003490+			
	<b>M010</b>	2003450+	M170+	F000+		
	<b>M020</b>	2004090+	M200+	M050+		
	<b>M030</b>	2004410+	M220+	M070+		
	<b>M040</b>	2004410+	M240+	M100+		
	<b>M050</b>	2005030	M260	M130+		
	<b>M060</b>	2005030	M260	M170+		
	<b>M070</b>	2005030	M260	M200+	F000+	M070 will also mark the last release where Pro/ENGINEER 2001 and Pro/ENGINEER Wildfire will be supported.
	<b>M080</b>			M220+	M020+	

## Windchill 6.2.6 Series Compatibility

		Pro/ENGINEER Release			Notes
		2001	Wildfire	Wildfire 2.0	
<b>Windchill 6.2.6 Release</b>	<b>DSU6</b>	2003450+	2003490+	-	
	<b>DSU7</b>	2003450+	2003490+	-	
	<b>DSU8</b>	2003450+	M170+	F000+	
	<b>DSU9</b>	2004290+	M210+	M050+	
	<b>DSU10</b>	2004410+	M230+	M080+	
	<b>DSU11</b>	2004410+	M240+	M110+	
	<b>DSU12</b>	2005030+	M260+	M130+	
	<b>DSU13</b>	2005030+	M260+	M190+	

## Interoperability Notes

1. The Workgroup Manager for Pro/ENGINEER 2001 Java client must be downloaded from the Windchill server.  
The Workgroup Manager for Pro/ENGINEER Wildfire is embedded in Pro/ENGINEER Wildfire. Therefore it is no longer required that you download and install this Java client, which does not support Pro/ENGINEER Wildfire
2. Compatibility between Pro/ENGINEER Wildfire 2.0 and Windchill 6.2.6 will be supported until the last maintenance release of Windchill 6.2.6. Maintenance releases of Pro/ENGINEER Wildfire 2.0 delivered after the final maintenance release of 6.2.6 will not be qualified.
3. The Windchill Aerospace & Defense Module is available with Windchill 7.0 M030 and is compatible only with Pro/ENGINEER Wildfire 2.0.
4. The Windchill Aerospace & Defense Module support starts at Pro/ENGINEER Wildfire 2.0 M140 as of 8.0 F000.
5. Customers upgrading to Windchill 8.0 based solutions from previous Windchill releases, and customers migrating to Windchill 8.0 based solutions from Pro/INTRALINK 3.x must use M150 or later.

## Platform Support: Workgroup Manager for Pro/ENGINEER

			HPUX		Windows					IRIX	Solaris					Linux	
			11	11i	Vista	XP 64-bit	XP*	XP**	2000*	NT 4.0	6.5	2.6	7	8	9	10 Opteron	Red Hat
Windchill Release	6.2.6	2001	Y	Notes 1,2	N	N			Y	Y	Y	Y	Y	Y	N	N	N
		Wildfire	Y	Y	N	N	Notes 2,5	N	Y	Y	N	Y	Y	Y	N	N	N
		Wildfire 2.0	Note 4	Note 4	N	N	Notes 2,5	N	Y	N	N	N	N	Note 4	N	N	N
	7	2001	Notes 1,3	Y	N	N	Notes 5,6	N	Y	N	Note 3	N	N	Note 1	Note 1	N	N
		Wildfire	Note 3	Y	N	N	Notes 5,6	N	Y	N	N	N	N	N	Y	N	N
		Wildfire 2.0	Notes 3,4	Note 4	N	N	Notes 5,6	N	Y	N	N	N	N	Note 4	Note 4	N	N
		Wildfire 3.0	Notes 3,4	Note 4	N	N	Notes 5,6	N	Y	N	N	N	N	Note 4	Note 4	N	N
	8	Wildfire 2.0	N	Note 8	N	Note 9	SP2	SP2	SP4	N	N	N	N	Note 4	Note 4	N	N
		Wildfire 3.0	N	Note 8	Note 11	Note 9	SP2	SP2	SP4	N	N	N	N	Note 4	Note 4	Note 10	N
		Wildfire 4.0	N	Note 8	Y	Note 9	SP2	SP2	N	N	N	N	N	Note 4	N	Note 10	N

- \* Professional
- \*\* Home Edition

## Platform Specific Notes:

1. On 64bit operating systems, Pro/ENGINEER 2001 must be run in 32bit mode in order to be compatible with the Windchill Workgroup Manager for Pro/ENGINEER 2001.
2. Requires Windchill 6.2.6 DSU9.
3. Requires Windchill 7.0 M010.
4. 64 bit only.
5. Please refer to [TAN# 124940](#) that describes a problem with the scrolling of certain pages on Windows XP.
6. Service Pack 2 supported beginning with Windchill 7.0 M030
7. 64 bit only PA8000 or later
8. HPUX 11i V1 (PA-RISC)
9. Pro/ENGINEER Wildfire 2.0 (M210 and above) and Pro/ENGINEER Wildfire 3.0 (M020 and above) interaction with Windchill 8.0 M020 is now supported on 64-bit Windows XP (Opteron and EM64T), but any applets that are accessed through the embedded browser will not work, because there is no 64-bit Java Plug-in currently available. Any access to applets would need to be executed from a standalone browser running in 32-bit mode. For more information on this Java Plug-in issue please refer to [TPI 132924](#). Starting with 8.0 M050, this also applies to Pro/ENGINEER Wildfire 4.0 (F000 and above). For more information on Windchill supported clients please refer to the Windchill 8.0 Software Matrices located at the following URL: [http://www.ptc.com/view?im\\_dbkey=26238](http://www.ptc.com/view?im_dbkey=26238)
10. Solaris 10 on Opteron is a supported client platform for Pro/ENGINEER Wildfire 3.0 interaction as of 8.0 M020 of Windchill.
11. Client support for Windows Vista is available starting with Windchill 8.0 M045 and Pro/ENGINEER Wildfire 3.0 M120.