

Mapping ProE common name To PDMLink Name

🛄 New									
Type Type Sketch Sketch Part Assemb Manufac Manufac Manufac Format Format Report Layout Markup	cturing O Bulk O Harness								
Name	NEW_SOLID_PART								
Common Name	on Name DESCR FROM COMM NAME								
🗌 Use default template									
ОК	Cancel								

New File Options		×
- Template		
part_template	Browse.	-
[Farati		
Empty mmns_part_solid		
part_sheetmetal_template		
part_template		
Parameters		_
DRAWN_BY	DMM	ור
DESCRIPTION		-11
	120ct11	
MATERIAL	JUNK	
CHANGE_DESCRIPTION		
CUSTOMER_PART_NUMBER	N/A	
BLANK_SIZE		
CUSTOMER	BOB'S BIG HOUSE OF JUNK	
ENGINE_MAKE		
ENGINE_MODEL		
COATING	GOO	
Copy associated drawings		
OK	Cancel	



Save Object	×
	template change on R 🔻 🐓 Search
🖣 Organize 🗸 🏢 Views 🗸	Tools 🗸 🦃
Common Folders	🚞 .
🖃 🕆 Workspace	
🕜 Desktop	
🖄 My Documents	
🖳 rcp12	
😭 Working Directory	
🔠 Network Neighborhood	
Favorites	
► Folder Tree	
Model Name NEW_SOLID	_PART.PRT
Save To	
ОК	Cancel



Object List (2 of 2 total objects)										-	?							
File ▼ Edit ▼ Tools ▼																		
	Remov	ve l	t. Upload	Check In	Check Out	Undo Check Out	인 Update Auto A	್ರ್ರೆ ssociate Parts	B	ैं <u>New Part</u>	Create CAD Document	Add	Find in List					
	tt 1	t1		Number				File Name				Actions	Vers	Last Modified	State	Name		
	+	*	L_	NEW_S	V_SOLID_PART.DRW				new_solid_part.drw				û 🔲 🏚 🎒	1.0	2011-10-12 16:2	Design	new_solid_pa	art.drw
	+	*		NEW_S	OLID_PAR	T.PRT		new_solid_	part.prt				0 🔲 🔶 🦺	1.0	2011-10-12 16:2	Design	new_solid_pa	art.prt
((0 objects selected)																	